



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/Client 50005DE0028/1

Work Order Type: Weatherization

Audit Name: Audit DE0028

CLIENT INFORMATION

Client Name:

Address:

Client ID: Client 50005DE0028

Alt. Client ID:

AGENCY INFORMATION

Agency: 50005DE

Agency Phone: (901) 476-5226

Address: P. O. BOX 634, 915 HWY 51 SOUTH
COVINGTON, TN 38019

Fax: (901) 476-5258

Email Address: gloria.v.williams@tn.gov

Agency Contact: Treadwell, Dwight

Work Phone: (901) 274-8336

Cell Phone: (865) 335-4834

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: Client 50005DE0028

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0028/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 5

Measures

Measure 1 Infiltration Redctn

Components

Inspected

Comment AIR INFILTRATION MEASURES

☐

1. Seal around water heater and hood vent flue areas
2. Seal around crown molding in all
3. Weatherstrip attic access door
4. Air seal all plumbing penetrations - kitchen and bathroom
5. Wrap all 7 boots and air seal with mastic tape and sealer
6. Weatherstrip Front & Back doors
7. Doorsweep back door

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 DWH Pipe Insulation

Components

Inspected

Comment

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: Client 50005DE0028

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0028/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 5

Measure 3 Wall Insulation**Components** Back,Front,North,South**Inspected****Comment** Recommend adding dense pack R-13 cellulose from the outside - remove and replace vinyl siding to insulate walls☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1095	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		
						<input type="text"/>			

Field Notes:**Measure 4 Attic Ins. R-38****Components** 1107 Sq.ft**Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1107	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		
						<input type="text"/>			

Field Notes:

Client Name:

Client ID: Client 50005DE0028

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0028/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 5

Measure 5 Replace Htg. System**Components** Main

Inspected

Comment

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	Replacement Furnace - 80 kBtu/h NG Existing, 40 - 56 kBtu/h NG Post	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Replacement Furnace - 80 kBtu/h NG Existing, 40 - 56 kBtu/h NG Post	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 6 CO Monitor is Needed**Components**

Inspected

Comment

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: Client 50005DE0028

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0028/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 5

Measure 7 Fix Gas Leak Present (Cook Stove)**Components****Inspected**

Comment Current stove is 25 years old and has a gas leak at back eye - Oven door is broken - Recommend replacing this stove

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total: **Sub Total:** **Field Notes:****Work Order Grand Total:** **Grand Total:**

Client Name:

Client ID: Client 50005DE0028

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/Client 50005DE0028/1

Report Run On: 5/23/2010

DOE Weatherization Assistant

Version 8.5.0

Page 5 of 5